

T-400 ALUMINUM DIRECT DRUM

Part #405711 - 405712 - 405721 - 405722 - 405724

Forward clutch drum side

Instructions

ATI recommends the use of a bearing (ATI part #405701) in place of the OEM thrust washer to avoid damage to the direct drum. If a bearing is used, cut the forward clutch hub .035" for proper clearance.

Note! The direct drum must float between forward clutch hub and sun gear tube.

